

ID	Name	Concern Type	Comments	Submission Method	Date Submitted	Type/Note	Address
1	Joe Krusinski	a pond or detention basin overflows	Concern provided in 5 separate emails on 2/8/2021	Online application, additional information by email	2/8/2021	Associated with known project area	Mettawa Woods Drive cul de sac
2	Lawrence Falbe	other (describe in section below)	We don't have any stormwater concerns; we have an dedicated easement for drainage on the north side of our lot that conveys flow from west to east, with a large stormwater drain on the east corner of our lot. It seems to work well even in periods of heavy rain when we get a bit of a river flowing west to east in the backyard.	Online application	2/8/2021	No issue	
3	Chris Lane	other (describe in section below)	Rain water runs along Westwoods In. and under (and over with heavy rains)my driveway. It has started to erode the driveway.	Online application	2/8/2021	Private	
4	Stephen Baez	other (describe in section below)	Water from heavy rainstorm washing debris into intersection of Bradley and Old School Road. This debris is a hazard to Bicyclists traveling down Old School Road and turning South onto Bradley Road. I have personally witnessed a cyclist wipe out on this debris.	Online application	2/8/2021	Recommend minor inlet adjustment	W Old School Road and Bradley Road
5	Angelo Boulieris	other (describe in section below)	Flooding overflow from Bradley Road, draining down Mettawa Lane Rd and onto the yards seen in the attached pictures.	Online application, additional information by email	2/8/2021	Associated with known project area	Mettawa Lane
6	Les Raffel	flooding from a river, stream, or creek	Several years ago, a culvert was constructed under Little St. Marys Road that directed water from the east side of the road to the west side onto my property. This has caused erosion on my property and as formed a breeding area for mosquitos.	Email	2/9/2021	Associated with known project area	15390 W Little Saint Marys Road
7	Matthew Witten	flooding from a river, stream, or creek	There is a massive amount of water run off from Oasis Park, which floods over the top of the private road at south end of our property. The creek also floods at other locations near the north end of our property as the culverts on Mettawa Lane are overwhelmed by the water pouring through. It has increased significantly over the past few years, as more and more of the village water is directed through this area. I am also attaching a letter from all of the concerned and frustrated residents of this area, who continue to experience flooding and erosion. We will send video files, as the file sizes are too large for attachment. We request that someone come out to meet with us and view the area and walk through the issues that are occurring. Please contact us to schedule.	Online application, additional information by email	2/9/2021	Associated with known project area	Bradley Oasis Park Area
8	Tim Towne	standing water or ice on a roadway	Stormwater exits storm sewer from corporate way farm into Riteway rd ditch from corporate way farm then flows easterly along ditch until bend in Riteway rd, then during heavy rain events, due to ditch not being properly graded during construction of corporate way stable flows out onto Riteway rd and floods the road creating standing water or ice on pavement depending on time of year. Corporate way farm was a new subdivision and the subdivision control ordinance provides retention for all new subdivisions, and they never provided retention violating both the Storm Water Management ordinance as well as the village subdivision control ordinance which states all new subdivisions provide their own retention ponds. Anderson engineering, specifically Jamie Abderson, has many videos that were provided by me during these storm events and have not sufficiently solved the problem. I would be happy to meet and discuss the matter and show you those videos if Anderson can't provide them to you.	Online application	2/9/2021	Private	
9	Brian and Cindy Klassman	standing water in an unpaved area (grass, woods)	On heavy rains or defrost, the swale on south side of old school rd, isn't able to handle the water flow.	Email	2/9/2021	Private	
10	Karen Carruthers	standing water in an unpaved area (grass, woods)	SE corner of Rt 60 & Riverwoods Rd, between Costco & Rt 60 - historical GIS aerial photos (and dead tree remains) indicate that healthy tree cover extended ~100' further west (closer to Riverwoods Rd) than it does now. Cattails & phragmites now dominate the western third of this village-owned parcel, indicating standing water and likely interrupted drainage.	Online application	2/9/2021	Village to decide if and how to proceed with this open space	Riverwoods Road and Townline Road

ID	Name	Concern Type	Comments	Submission Method	Date Submitted	Type/Note	Address
11	A. H. Gerhardt	a pond or detention basin overflows	Good day, There is a detention basin for the Mettawa Woods Drive subdivision located between the former Korhumel home (north side of Highway 60 and roughly 200 yards west of Riverwoods Road) and our residence at 14155 Mettawa Woods Drive. This is roughly 1.1 acres in surface area, since created it has become overgrown with cattails, and our residence has seen a few instances where heavy rainfall has produced high water levels with standing water in our yard. Is this due to poor maintenance by our subdivision? Or the cattails blocking water flow? Thanks for your consideration, it would be a pleasure to discuss further.	Online application	2/9/2021	Associated with known project area	Mettawa Woods Drive cul de sac
12	A. H. Gerhardt	a pond or detention basin overflows	Good day, There is a detention basin for the Mettawa Woods Drive subdivision located between the former Korhumel home (north side of Highway 60 and roughly 200 yards west of Riverwoods Road) and our residence at 14155 Mettawa Woods Drive. This is roughly 1.1 acres in surface area, since created it has become overgrown with cattails, and our residence has seen a few instances where heavy rainfall has produced high water levels with standing water in our yard. Is this due to poor maintenance by our subdivision? Or the cattails blocking water flow? Thanks for your consideration, it would be a pleasure to discuss further.	Online application	2/9/2021	Associated with known project area	Mettawa Woods Drive cul de sac
13	Sean McCarthy	other (describe in section below)	Lack of upkeep and overgrown vegetation in culverts that no longer work, that are now causing erosion to roads and redirecting rain water towards homes.	Online application	2/9/2021	Village to address Little Melody Ln in 2023	
14	A. H. Gerhardt	a pond or detention basin overflows	There is a detention basin for the Mettawa Woods Drive subdivision that is currently overgrown with cattails. Our residence at 14111 Mettawa Woods Drive has had several episodes of standing water following periods of heavy rainfall. Is this due to inadequate maintenance? Or possibly the cattails blocking water flow? It would be a pleasure to discuss further. Thanks for your consideration.	Online application	2/9/2021	Associated with known project area	Mettawa Woods Drive cul de sac
15	Holly Hirsch	other (describe in section below)	I have standing water on my property driveway and on unpaved area along oasis service road, flooding from ditch, Oasis Park overflows onto Oasis Service Road my property. Damage and erosion is occurring on unpaved area and paved area due to water. Trees are falling down and driveway is ruined. The berm has created more water. The drainage improvements on Bradley have allowed more water to to the ditch increasing flooding. I had a cyber attack lost many pictures and videos sent to the village.	Online application, additional information by email	2/12/2021	Associated with known project area	Bradley Oasis Park Area
16	John Bradley	other (describe in section below)	Storm water failing on many levels. On Riverwoods Rd and Little Melody Rd water either drains into homeowner's yards or floods the street. The ground has built up in the grass swales where it does not allow the water to flow to the retention areas that have been made for it. In some areas the piping under the driveways leading from the streets which is to allow the water to flow as well has fallen apart or been crushed due to the streets sinking. Many homeowners have tried to dig these areas up and fix them themselves to help solve the problems. Due to the snow pictures cannot be taken to show these problems although I have sent pictures a year or two ago for he Village to review and will try and find them and send them again.	Online application	2/12/2021	Village to address Little Melody Ln in 2023	
17	Mary Brennan	standing water or ice on a roadway	Culver of Little St. Marys Road by home #15141... is too small so it overflows on the road	Mail	2/12/2021	Associated with known project area	15141 W Little Saint Marys Road
18	Mona Nicholas	other (describe in section below)	The cement culvert on the corner of my property located near the intersection of Meadowoods + Southwoods is out of place. Now stormwater flows around it under it instead of through it.	Email	2/12/2021	Associated with known project area	27115 Meadowoods Drive
19	Margo and Mike Oberman	standing water or ice on a roadway	We have never experienced a problem. Thank you!	Online application	2/12/2021	No issue	
20	Robert Pauls	other (describe in section below)	Hi there. We moved in last September and soon after noted that we had the output of either a breached municipal pipe or a spring on our property. (We believe it is likely the latter.) the bubbling of water to the surface actually causes significant flooding in our property, and we have wondered if there are any solutions we might be able to employ in order to limit the amount of standing water that this regularly creates.	Online application	2/15/2021	Private - Hey confirmed very likely tile failure	

ID	Name	Concern Type	Comments	Submission Method	Date Submitted	Type/Note	Address
21	George Ginakakis	other (describe in section below)	I spoke with Dave from Hey & Assoc. over the phone and he advised that I document flooding issues here. Drainage Ditch on the East side of St. Marys Rd. just north of Rt. 60 has lost its definition in a particular area (about 3 driveways north of rt. 60. The water in this drainage ditch it supposed to flow North on St. Marys rd. downhill, however over time the drainage ditch has lost the definition to its swale and now the water floods into the properties East of St. Marys rd.- instead the water should continue down the drainage ditch to the North. I have been following this flooding issue over the past couple of years and trace back the neighbors flooding to this area. I believe this drainage ditch needs to be redefined here so that the water continues North down the drainage ditch as intended. Please contact me with any questions or to discuss. I would be more than happy to meet someone from Hey & Assoc. in the field when you are in the area next. -George (847)340-2111	Online application	2/17/2021	Private	
22	Stevie Schmidt	standing water or ice on a roadway	Village pipe at the end of driveway, on old school rd, has raised up and is causing a large bump while walking on driving out. Situation is getting worse every year.	Email	2/20/2021	Private	
23	Bill Kurtis and Donna LaPietra	standing water or ice on a driveway		Email	2/20/2021	Private	
24	Leslie K. Haines	flooding from a river, stream, or creek		Mail	2/24/2021	Private	
25	Nicholas Papanos	standing water in an unpaved area (grass, woods)	We have experienced significant standing water/flooding in our backyard which is adjacent to the Village's Oasis Park property during rain storms. We have been living here since Dec 2002 and we did not have as much of a problem until the berms at the Oasis Park were constructed a few years back. Since then, the flooding in the backyard has been very significant. We were told by the Village engineer that one of the Village's retention ponds may be the problem, especially when it becomes clogged, but we feel more needs to be evaluated with a more definitive and consistent resolution to the problem. This flooding has eroded that area in our backyard.	Online application, additional information by email	2/25/2021	Private, associated with HOA detention maintenance	
26	Mary Swift	standing water in an unpaved area (grass, woods)	The wooded areas of our front and side property are often flooded after storms and heavy melting of snow and ice. Some flooding does reach into the street. All these areas can collect extreme amounts of water, which often sits for prolonged periods of time and can also run onto the street. We have multiple sump pumps in our home and when the ground is wet or saturated (which it most often is -- aside from the freezing winter months) our pumps can run consistently for days to weeks without stopping. Our concern is not only the visible, standing water in our woods and on our street but also the excessive volume of ground water that does not seem to drain properly and keeps our sump pumps running nearly constantly after the winter months.	Online application	2/26/2021	Associated with known project area	15390 W Little Saint Marys Road
27	Joseph Lafita	standing water in an unpaved area (grass, woods)	During heavy (and not so heavy) rain fall, we have a pond/river running through the north and south sides of our property. The entire fields are also very swampy for a long time.	Online application	2/26/2021	Private	
28	Brett Wiegman	standing water or ice on a driveway	During large-scale weather events with lots of rapid rain, we have water that moves from the east of our property to the west where our pond is. In extremely heavy rains, we have had water overflow the culvert and our driveway, washing out the area completely	Email	3/5/2021	Private	
29	Ann and Thomas A. Heinz	Standing water in an unpaved area (grass, woods)	With heavy rains, the front yard, across the entire frontage, floods, across the road, St Marys, it sometimes crosses.	Mail	2/26/2021	Private	
30	Ninette Viglione	A pond or detention basin overflows	This retention pond is on adjacent property (lot to the west) During excessive rainfall, runoff was coming from neighbors property that is north of ours and more elevated than ours.	Email	3/5/2021	Private	
31	R Busscher	other (describe in section below)	We have no water issues at this time.	Mail	2/28/2021	No issue	